Arm SystemReady certification: SystemReady ES V1.1 (Level 1)

Company:	NXP
System:	Layerscape LS1046A Reference Design Board (RDB)
SoC family:	NXP LS1046A
Firmware version:	• Layerscape Software Development Kit 21.08 (flexbuild_lsdk2108)
Additional information:	Layerscape SDK support site
ACS version:	SystemReady ES ACS v1.0
BSA details:	BSA v1.0
BBR details:	SBBR (BBR 1.0)
Tested operating systems:	 VMware ESXi-Arm Fling v1.8 Fedora Server 35 Ubuntu Server 21.10 openSUSE Tumbleweed 20210901 Debian 11.0 CentOS Stream 9
Date issued:	01-25-2022





Arm SystemReady certification: SystemReady ES V1.0 (Level 1)

Company:	NXP
System:	Layerscape LS1046A Reference Design Board (RDB)
SoC family:	NXP LS1046A
Firmware version:	 EDK2 REL5.2 (12/1/2020) Layerscape LS1046A Reference Design Board (RDB)
Additional information:	Certification Errata
ACS version:	Enterprise ACS v2.5
BSA details:	BSA v1.0 (currently tested with ACS for SBSA Level 3)
BBR details:	SBBR (BBR 1.0)
Tested operating systems:	 VMware ESXi-Arm Fling v1.0 CentOS 8.2 (*) Debian 10.4 (*) Ubuntu 20.04 (*) Fedora Server 32 (*) Fedora Workstation 34 *OS tested using PCle video card graphics console
Date issued:	08-06-2021





Arm SystemReady certification: SystemReady ES V1.1 (Level 1)

Company:	NXP
System:	Layerscape LS1046A Freeway board (FRWY)
SoC family:	NXP LS1046A
Firmware version:	• Layerscape Software Development Kit 21.08
Additional information:	 LS1046AFRWY-LSDK21.08 firmware prebuilt images and patches Layerscape SDK support site
ACS version:	SystemReady ES ACS v1.0
BSA details:	BSA v1.0
BBR details:	SBBR (BBR 1.0)
Tested operating systems:	 VMware ESXi-Arm Fling v1.8 Fedora Server 35 Ubuntu Server 21.10 openSUSE Tumbleweed 20211202 Debian 11.2 CentOS Stream 9
Date issued:	02-16-2022





Arm SystemReady certification: SystemReady ES V1.0 (Level 1)

Company:	NXP
System:	Layerscape LS1046A Freeway board (FRWY)
SoC family:	NXP LS1046A
Firmware version:	EDK2 REL5.2 (12/1/2020)Layerscape SDK version 20.12 (flexbuild_lsdk2012)
Additional information:	Certification ErrataLayerscape SDK support site
ACS version:	Enterprise ACS v2.5
BSA details:	BSA v1.0 (currently tested with ACS for SBSA Level 3)
BBR details:	SBBR (BBR 1.0)
Tested operating systems:	 VMware ESXi-Arm Fling v1.1 Fedora Server 34 Fedora Workstation 34 Open SUSE Tumbleweed Snapshot 2021020
Date issued:	08-06-2021





Arm SystemReady certification: SystemReady ES V1.0 (Level 1)

Company:	NXP
System:	Layerscape LX2160A Reference Design Board (RDB)
SoC family:	NXP LX2160A
Firmware version:	LX2RDB_SYS_READY_TAG_01Layerscape SDK version 20.12 (flexbuild_lsdk2012)
Additional information:	Layerscape SDK support site
ACS version:	Enterprise ACS v2.5
BSA details:	BSA v1.0 (currently tested with ACS for SBSA Level 3)
BBR details:	SBBR (BBR 1.0)
Tested operating systems:	 Windows PE (10.0.19041.1) VMware ESXi-Arm Fling v1.1 Ubuntu Server 20.04 Fedora Server 32 Debian 10.4.0 CentOS 8.2 OpenSUSE Leap 15.2
Date issued:	11-10-2020



